

# Oil Field Environmental Incident Summary

**Incident:** 20160606110341 **Date/Time of Notice:** 06/06/2016 11:03

**Responsible Party:** PETRO-HUNT, L.L.C.

**Well Operator:** PETRO-HUNT, L.L.C.

**Well Name:** USA 153-95-22C-15-3H

**Field Name:** CHARLSON

**Well File #:** 26214

**Date Incident:** 6/5/2016 **Time Incident:** 09:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 153

**Rng:** 95

**Sec:** 22

**Qtr:**

**Location Description:**

**Submitted By:** Shawn Reisenauer

**Received By:**

**Contact Person:** Shawn Reisenauer  
390 119th Ave SW  
Killdeer, ND 58640

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	50	Barrels	40	Barrels	50	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 7/27/2016

**Clean Up Concluded:** 7/25/2016

**Risk Evaluation:**

none

**Areal Extent:**

**Potential Environmental Impacts:**

None. All fluids remained in diked area, however a tear in the dike liner allowed fluids to seep through. Approx. 40 bbls vacced up and recycled onsite. The remaining contaminated soil will be dug up and replaced with clean soils.

**Action Taken or Planned:**

Spill response and clean up was well handled.

**Wastes Disposal Location:** Secure/PDI

**Agencies Involved:**

**Updates**

---

**Date:** 6/6/2016      **Status:** Reviewed - Assigned to Other Agency

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report the release remained within the well pad perimeter. NDIC takes oversight.